Before the Federal Communications Commission Washington, D.C. 20554

| In the Matter of |) | |
|--|---|----------------------------------|
| |) | |
| Amoco Production Company |) | File No.: EB-FIELDWR-13-00012912 |
| Owner of Antenna Structure No. 1024687 |) | |
| |) | NOV No.: V201432800019 |
| Oxford CO | ĺ | |

NOTICE OF VIOLATION

Released: March 19, 2014

By the District Director, Denver District Office, Western Region, Enforcement Bureau:

- 1. This is a Notice of Violation (Notice) issued pursuant to Section 1.89 of the Commission's rules (Rules)¹ to Amoco Production Company (Amoco), registrant of antenna structure # 1024687 by Oxford, CO. Pursuant to Section 1.89(a) of the Rules, issuance of this Notice does not preclude the Enforcement Bureau from further action if warranted, including issuing a Notice of Apparent Liability for Forfeiture for the violations noted herein.²
- 2. On December 11 and again on December 12, 2013, an agent of the Enforcement Bureau's Denver District Office inspected antenna structure # 1024687 located at 37° 10' 8.9" north latitude and 107° 44' 58.2" west longitude, and observed the following violations:
 - a. 47 C.F.R. § 17.4(g): "...the Antenna Structure Registration Number must be displayed in a conspicuous place so that it is readily visible near the base of the antenna structure. Materials used to display the Antenna Structure Registration Number must be weather-resistant and of sufficient size to be easily seen at the base of the antenna structure." The agent observed and an employee of the registrant confirmed that the antenna structure registration number was not displayed.
 - b. 47 C.F.R. § 17.23: "each new or altered antenna structure to be registered on or after January 1, 1996, must conform to the FAA's painting and lighting recommendations set forth on the structure's FAA determination of "no hazard,"..." The FAA recommended that antenna structure 1024687 be painted and lit in accordance with Chapter 3, 4, 5, and 9 of FAA Circular 70/7460-1G. Chapter 5 specifies red lights. However, during the night-time

¹ 47 C.F.R. § 1.89.

² 47 C.F.R. § 1.89(a).

- observations on December 11 and December 12, 2013, the agent observed no lights working on the antenna structure.
- c. 47 C.F.R. § 17.57: "The owner of an antenna structure for which an Antenna Structure Registration Number has been obtained must notify the Commission within 24 hours of completion of construction (FCC Form 854-R) and/or dismantlement (FCC Form 854). The owner must also immediately notify the Commission using FCC Form 854 upon any change in structure height or change in ownership information." The agent's investigation found that the owner's phone number on the Antenna Structure Registration was not valid.
- 3. Pursuant to Section 403 of the Communications Act of 1934, as amended,³ and Section 1.89 of the Rules, we seek additional information concerning the violations and any remedial actions taken. Therefore, Amoco must submit a written statement concerning this matter within twenty (20) days of release of this Notice. The response (i) must fully explain each violation, including all relevant surrounding facts and circumstances, (ii) must contain a statement of the specific action(s) taken to correct each violation and preclude recurrence, and (iii) must include a time line for completion of any pending corrective action(s). The response must be complete in itself and must not be abbreviated by reference to other communications or answers to other notices.⁴
- 4. In accordance with Section 1.16 of the Rules, we direct Amoco to support its response to this Notice with an affidavit or declaration under penalty of perjury, signed and dated by an authorized officer of Amoco with personal knowledge of the representations provided in Amoco's response, verifying the truth and accuracy of the information therein,⁵ and confirming that all of the information requested by this Notice which is in the licensee's possession, custody, control, or knowledge has been produced. To knowingly and willfully make any false statement or conceal any material fact in reply to this Notice is punishable by fine or imprisonment under Title 18 of the U.S. Code.⁶
- 5. All replies and documentation sent in response to this Notice should be marked with the File No. and NOV No. specified above, and mailed to the following address:

³ 47 U.S.C. § 403.

⁴ 47 C.F.R. § 1.89(c).

⁵ Section 1.16 of the Rules provides that "[a]ny document to be filed with the Federal Communications Commission and which is required by any law, rule or other regulation of the United States to be supported, evidenced, established or proved by a written sworn declaration, verification, certificate, statement, oath or affidavit by the person making the same, may be supported, evidenced, established or proved by the unsworn declaration, certification, verification, or statement in writing of such person Such declaration shall be subscribed by the declarant as true under penalty of perjury, and dated, in substantially the following form . . . : 'I declare (or certify, verify, or state) under penalty of perjury that the foregoing is true and correct. Executed on (date). (Signature)'." 47 C.F.R. § 1.16.

⁶ 18 U.S.C. § 1001 et seq. See also 47 C.F.R. § 1.17.

Federal Communications Commission

Federal Communications Commission Denver District Office P.O. Box 25446 One Denver Federal Center – Building 1A Lakewood, CO 80225

- 6. This Notice shall be sent to Amoco Production Company at its address of record.
- 7. The Privacy Act of 1974⁷ requires that we advise you that the Commission will use all relevant material information before it, including any information disclosed in your reply, to determine what, if any, enforcement action is required to ensure compliance.

FEDERAL COMMUNICATIONS COMMISSION

Nikki P. Shears District Director Denver District Office Western Region Enforcement Bureau

-

⁷ P.L. 93-579, 5 U.S.C. § 552a(e)(3).